

17.3.81
275
8/11

DC Perdony

From
The Member-Secretary,
Madras Metropolitan
Development Authority,
No.8, Gandhi-Irwin Road,
Madras-600 008.

To
M. Metilda,
Mother General
St. Louis Convent
St. Thomas Mount
Madras-16.

Letter No. C4/29948/92

Dated: 6.93.

Sir,

Sub: MMDA-PP - Regularisation of Existing
~~two~~ building and additional construction of
school building at S.No. 564/1B and 575/2
of Velachery village - appd - Remittance of
Ref: D.C. Reg.

Ref: Ccm L. WDC-N? . D10/PPA 7736/92 dt. 9.12.92

The proposal received in the reference cited
for the ~~construction~~ regularisation of Existing school building
and additional construction of school building at S.No. 564/1B
and 575/2 of Velachery village

has been examined and you were requested to submit the
revised plans to satisfying rules. The revised plans
submitted by you directly to this office was examined
and found approvable.

① and a sum of
Rs. 1000/- (Rupees
one thousand
only) towards
Surveying fee

2. In this connection, you are requested to remit
a sum of Rs. 2,100/- (Rupees two thousand and one hundred only)
towards Development Charges for land and building by two
Demand Drafts of any nationalised bank in Madras, drawn
in favour of the Member-Secretary, MMDA or may be remitted
in cash at the cash counter of the MMDA within ten days
on receipt of this letter. You are also requested to
furnish an undertaking deed duly notarised, and the following particulars

u/b
DESPATCHED

3. On receipt of the amount, the approved plans
will be sent to the Commissioner, Corporation of Madras,
for further action. Madras-3.

4. For the payments received after one month,
interest will be collected at the rate of 12% per annum
(ie. 1% per month) for every completed month from the
date of issue of this advice.

Yours faithfully,

Encl: Copy of Undertaking Deed.

for MEMBER-SECRETARY.

Copy to: 1) The Commissioner
Corporation of Madras.

4/6
4/6

2) The S.A.D., Accounts (Main) Divn.

i) - Revised site plan showing the site boundary measurements tallying
with the FMS sketch.

ii) Revised site plan showing the setback measurements as on site condition
and ~~then~~ showing the correct S.No (tallying with patta) without any
corrections.

iii) Attached copy of the Layout No. LPDM/DTP 45/66.